






JAPAX			<<unit in mm>>		
Description	S k e t c h		Machine Model No.	Hole Size	Wire Size
RJA-1U			LUX-3	0.055 ^{+0.005} ₀	0.05
			LV-3	0.105 ^{+0.005} ₀	0.1
			LS 250 - 1000S	0.125 ^{+0.005} ₀	0.12
			LXE35 - 100	0.145 ^{+0.005} ₀	0.14
			LXR35 - 100	0.155 ^{+0.005} ₀	0.15
			LDM35 - 100	0.165 ^{+0.005} ₀	0.16
			LDM-S	0.205 ^{+0.005} ₀	0.2
				0.21 ^{+0.005} ₀	0.2
				0.255 ^{+0.005} ₀	0.25
				0.26 ^{+0.005} ₀	0.25
				0.305 ^{+0.005} ₀	0.3
				0.31 ^{+0.005} ₀	0.3
				0.315 ^{+0.005} ₀	0.3
				0.325 ^{+0.005} ₀	0.32
	0.375 ^{+0.005} ₀	0.35			
	Upper	033	169-G018		
RJA-2L			LUX-3	0.055 ^{+0.005} ₀	0.05
			LV-3	0.105 ^{+0.005} ₀	0.1
			LS 250 - 1000S	0.125 ^{+0.005} ₀	0.12
			LXE35 - 100	0.145 ^{+0.005} ₀	0.14
			LXR35 - 100	0.155 ^{+0.005} ₀	0.15
			LDM35 - 100	0.165 ^{+0.005} ₀	0.16
			LDM-S	0.205 ^{+0.005} ₀	0.2
			EX-P, EX-P20	0.21 ^{+0.005} ₀	0.2
				0.22 ^{+0.005} ₀	0.2
				0.255 ^{+0.005} ₀	0.25
				0.26 ^{+0.005} ₀	0.25
				0.27 ^{+0.005} ₀	0.25
				0.275 ^{+0.005} ₀	0.25
				0.305 ^{+0.005} ₀	0.3
	0.31 ^{+0.005} ₀	0.3			
	0.315 ^{+0.005} ₀	0.3			
	0.325 ^{+0.005} ₀	0.32			
	0.375 ^{+0.005} ₀	0.35			
	Lower	034	LUP-0181-BSA -D		
RJA-12L			LDM35 -AF4	0.12 ^{+0.005} ₀	0.1
			LDM50 -AF4	0.14 ^{+0.005} ₀	0.12
			LDM100 -AF4	0.17 ^{+0.005} ₀	0.15
			*AWT	0.18 ^{+0.005} ₀	0.16
			=Automatic Wire Threading	0.22 ^{+0.005} ₀	0.2
				0.27 ^{+0.005} ₀	0.25
				0.32 ^{+0.005} ₀	0.3
	Lower	063	949-C044		

Description	S k e t c h		Machine Model No.	Hole Size	Wire Size			
RJA-3U			LS 250A	0.055 ^{+0.005} ₀	0.05			
			L2 350A	0.105 ^{+0.005} ₀	0.1			
			LS 500A	0.145 ^{+0.005} ₀	0.14			
			LS 800A	0.155 ^{+0.005} ₀	0.15			
			LS 1000A	0.165 ^{+0.005} ₀	0.16			
				0.205 ^{+0.005} ₀	0.2			
				0.225 ^{+0.005} ₀	0.2			
				0.23 ^{+0.005} ₀	0.22			
				0.255 ^{+0.005} ₀	0.25			
				0.305 ^{+0.005} ₀	0.3			
				0.355 ^{+0.005} ₀	0.35			
				Upper	050	123-D315-01		
RJA-4L			LS 250A	0.055 ^{+0.005} ₀	0.05			
			L2 350A	0.105 ^{+0.005} ₀	0.1			
			LS 500A	0.145 ^{+0.005} ₀	0.14			
			LS 800A	0.165 ^{+0.005} ₀	0.16			
			LS 1000A	0.205 ^{+0.005} ₀	0.2			
				0.255 ^{+0.005} ₀	0.25			
				0.305 ^{+0.005} ₀	0.3			
				0.355 ^{+0.005} ₀	0.35			
				Lower	058	123-D389		
			RJA-5L			LS 250A	0.055 ^{+0.005} ₀	0.05
L2 350A	0.105 ^{+0.005} ₀	0.1						
LS 500A	0.145 ^{+0.005} ₀	0.14						
LS 800A	0.155 ^{+0.005} ₀	0.15						
LS 1000A	0.165 ^{+0.005} ₀	0.16						
	0.205 ^{+0.005} ₀	0.2						
	0.225 ^{+0.005} ₀	0.2						
	0.23 ^{+0.005} ₀	0.22						
	0.255 ^{+0.005} ₀	0.25						
	0.305 ^{+0.005} ₀	0.3						
	0.355 ^{+0.005} ₀	0.35						
	Lower	051				123-D386-01		